



# Tracer

## INDUSTRIAL FOOD SAFE DYE FOR HEAT TRANSFER FLUIDS

### Mixing Instructions

1. Ensure you are familiar with the dye SDS
2. Ensure appropriate PPE (Gloves & Eye Protection) is used during dye dosing.
3. Avoid contact with skin or clothing
4. Measure appropriate dye to be mixed into the HTF
5. Dilution Rate:
  - a. 500g / 1000kg for neat HTF
  - b. 250g / 1000kg for diluted/finished HTF

Qty to be Dyed	Dye Qty for diluted/finished	Dye Qty for neat
20kg	5g	10g
220kg	55g	110g
1000kg	250g	500g

6. Mix well

Please contact GSA technical staff for further advice